



BingoConsole E-max Tech Bulletin 10

Date Issued: 7/14/05

Product Effected: E-Max Console

Version(s) Effected: 1.3.3

Problem: Explains the problems that E-Max software version 1.3.3 fixes.

1. Corrected the camera not being set to the persisted activity (Game) camera setting in the Schedule. **See E-Max Tech Bulletin TB09 dated 5-4-05 for detailed problem description.**
2. Corrected the problem of when pressing a ball into the Tear-Open tray the ball is not updated on the console or flashboards. **See E-Max Tech Bulletin TB09 dated 5-4-05 for detailed problem description.**
3. Corrected the ball timer not counting down when a new ball is pressed into the ball tray.
4. Fixed ball tray bug that occurs when using RNG. (There were some problems with calling balls on the ball tray after calling RNG numbers.)
5. Disabled Up/Down arrows on the keyboard when the activity is an intermission.